





































































Nuts, Sleeves, Locknuts	BTX Nut  B9	TX and TX Metric Sleeve  B9	WLN Bulkhead Locknut  B10	SBR Braze Ring  B10	
	HTX Union  B10	LHTX Large Hex Union  B10	WTX Bulkhead Union  B11	WF50X SAE-ORB / 37° Bulkhead  B11	WFTX NPTF / 37° Bulkhead  B11
WGTX NPTF / 37° Bulkhead  B12	HHX6 Extender and Expander  B12	TRTX / TRTXN Reducer  B13	F50X SAE-ORB / 37° Flare  B14	FF50X SAE-ORB / 37° – Long  B14	XHB3 Braze Socket / 37° Flare  B14
FTX NPTF / 37° Flare  B15	FFTX NPTF / 37° Flare – Long  B15	GTX NPTF / 37° Flare  B15	F87OMX ISO 6149 / 37° Flare  B16	F82EDMX Metric-ED / 37° Flare  B16	F8OMX Metric-ORR / 37° Flare  B16
F42EDMX BSPP-ED / 37° Flare  B16	F4OMX BSPP-ORR / 37° Flare  B17	G4MX BSPP / 37° Flare  B17	F3MX BSPT / 37° Flare  B17	Straight Swivels	HX6 37° Swivel Union  B17
F650X SAE-ORB / 37° Swivel  B18	F6X NPTF / 37° Swivel  B18	G6X NPTF / 37° Swivel  B18	F687OMX ISO-6149 / 37° Swivel  B18		F68OMX Metric-ORR / 37° Swivel  B19
F642EDMX BSPP-ED / 37° Swivel  B19	F63MX BSPT / 37° Swivel  B19	45° Elbows	WNTX Bulkhead Union  B20	V6X 37° Swivel Elbow  B20	V50X SAE-ORB / 37° Flare  B20
V87OMX ISO-6149 / 37° Flare  B20	VTX NPTF / 37° Flare  B21		V4OMX BSPP-ORR / 37° Flare  B21	V3MX BSPT / 37° Flare  B21	90° Elbows
					ETX Union Elbow  B21

WETX Bulkhead Union  B22	C6X 37° Swivel Elbow  B22	AOEX6 SAE-ORB / 37° Swivel  B22	X6EF NPTF / 37° Swivel  B23	C50X SAE-ORB / 37° Flare  B23	CC50X SAE-ORB / 37° – Long  B23
CTX NPTF / 37° Flare  B24	CCTX NPTF / 37° Flare – Long  B24	CCCTX NPTF / 37° – Extra Long  B24	DTX NPTF / 37° Flare  B25	C87OMX ISO-6149 / 37° Flare  B25	C80MX Metric-ORR / 37° Flare  B25
C40MX BSPP-ORR / 37° Flare  B26	C3MX BSPT / 37° Flare  B26	Tees 	JTX Union Tee  B26	WJTX Bulkhead Branch Tee  B27	WJJTX Bulkhead Run Tee  B27
JX6 37° Swivel Union Tee  B28	S6X 37° Swivel Branch Tee  B28	R6X 37° Swivel Run Tee  B28	S50X SAE-ORB Branch Tee  B29	R50X SAE-ORB Run Tee  B29	STX NPTF Branch Tee  B30
RTX NPTF Run Tee  B30	OTX NPTF Branch Tee  B30	MTX NPTF Run Tee  B30	S87OMX ISO 6149 Branch Tee  B31	R87OMX ISO 6149 Run Tee  B31	S40MX BSPP-ORR Branch Tee  B31
R40MX BSPP-ORR Run Tee  B31	Cross 	KTX Union Cross  B32	Plug and Cap 	PNTX 37° Plug  B32	FNTX 37° Cap  B32
T22X Mountie Cap  B32					








Triple-Lok® 2 Soft Seal Flare Tube Fittings

	HTXO Union  B33	F5OXO SAE-ORB / 37° Flare  B33	FTXO NPTF / 37° Flare  B33	GTXO NPTF / 37° Flare  B33
	ETXO Union Elbow  B34	C6XO 37° Swivel Elbow  B34	CTXO NPTF / 37° Flare  B34	C5OXO SAE-ORB / 37° Flare  B34
	JTXO Union Tee  B35	RTXO 37° Swivel Run Tee  B35	R5OXO SAE-ORB Run Tee  B35	



Flange Adapters (Shown in Section L)

	XHQ1 Code 61 / 37° Flare  L12	XHQ2 Code 62 / 37° Flare  L12	XVQ1 Code 61 / 37° Flare  L30	XVQ2 Code 62 / 37° Flare  L30	XEQ1 Code 61 / 37° Flare  L31
XEQ2 Code 62 / 37° Flare  L31					


Conversion Adapters (Shown in Sections J and K)

	XHU86 Metric Swivel (EO) / 37°	XHMK4 Komatsu 30° / 37° Flare	XHMK46 Komatsu 30° Swivel / 37°	XHLO 37° Flare / ORFS	XHL6 37° Flare / ORFS Swivel
	 K5	 J5	 J5	 K3	 K3
LOHX6 ORFS / 37° Swivel	XHBU 37° Flare / Flareless	XHMK46 37° Flare / BSPP Swivel	XEMK46 37° Flare / BSPP Swivel		
 K3	 K4	 K5	 K5		


Diagnostic and Orifice Fittings (Shown in Section M)

	XHX6G5TP 37° Flare / 37° Swivel / SAE-ORB		XHX7 37° Flare / 37° Female with Orifice
	 M5		 M9








Gauge Fittings (Shown in Section M)

	G6X NPT Gauge / 37° Swivel	G4MXSMO BSPP Gauge / 37° Flare
	 M7	 M6

Screen Fittings (Shown in Section M)

	Screen Fittings
	 M12

O-Rings and Seals (Shown in Section N)

	XO O-Ring	SAE O-Ring	ISO 6149 O-Ring	Metric O-Ring	Metric Retaining Ring
	 N4	 N4	 N5	 N5	 N5
BSPP O-Ring	BSPP Retaining Ring	EOLastic Seal Ring			
 N6	 N6	 N6			